



Front View




- | | |
|--------------------------|-----------------|
| Loose/broken/delaminated | Previous repair |
| Damage/wear/hole | Replaced piece |

Rear View




- | | |
|-------------------------------|--------------|
| Missing | Add-ons |
| Spindles not original to desk | Inscriptions |


Right Side







Left Side





Top




 Loose/broken/delaminated
 Damage/wear/hole

 Previous repair
 Replaced piece

 Missing
 Spindles not original to desk

 Add-ons
 Inscriptions


Bottom



Loose/broken/delaminated
Damage/wear/hole

Previous repair
Replaced piece


Bottom




Missing
Spindles not original to desk

Add-ons
Inscriptions

Drawer Front, Outer Surface



Rear Surface of Drawer Front




■ Loose/broken/delaminated
■ Damage/wear/hole

■ Previous repair
■ Replaced piece


■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Inside Surface of Left Drawer Side




Inside Surface of Right Drawer Side




- | | | | |
|--|---|---|--|
|  Loose/broken/delaminated |  Previous repair |  Missing |  Add-ons |
|  Damage/wear/hole |  Replaced piece |  Spindles not original to desk |  Inscriptions |

Rear Surface of Drawer Back




Front Surface of Drawer Back




- | | | | |
|--|---|---|--|
|  Loose/broken/delaminated |  Previous repair |  Missing |  Add-ons |
|  Damage/wear/hole |  Replaced piece |  Spindles not original to desk |  Inscriptions |

Upper Surface of Drawer Bottom



Lower Surface of Drawer Bottom



■ Loose/broken/delaminated
■ Damage/wear/hole



■ Previous repair
■ Replaced piece

■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side




 Loose/broken/delaminated

 Damage/wear/hole


 Previous repair

 Replaced piece

 Missing

 Spindles not original to desk

 Add-ons

 Inscriptions